Approved For Release 2008/02/01 : CIA-RDP78B04558A001000030015-2

OUT56727

multi

P 202004Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 5485.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 7 WAS USED IN MISSION 8044 FLOWN ON 17 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

21 SEP 1965
COPIES RECEIVED

Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	~~CSD~~	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	✓
	PID	
	PAG	
	DIAXX 4	
	SPAD	
	NSA [illegible]	
	DIA [illegible]	

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. 9R SIDE: A NUMBER OF FINE PLUS DENSITY STREAKS RUN PARALLEL TO AND WITHIN THREE INCHES OF THE OUTBOARD EDGE OF THE FILM. THE NUMBER OF STREAKS VARIES FROM ONE TO THREE, WITH APPROXIMATELY 0.50" SPACING BETWEEN STREAKS WHEN MORE THAN ONE ARE PRESENT. A FEW IRREGULAR PLUS DENSITY STREAKS APPEAR ON THE INBOARD EDGE IN FRAMES 1441 TO 1680. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 364. A BREAKDOWN SPLICE IS POSITIONED INSIDE FRAME 981.

C. 9L SIDE: FRAMES 002 TO 200 CONTAIN A ROW OF MINUS DENSITY DOTS PARALLEL TO AND 3.75" FROM THE OUTBOARD EDGE OF THE FILM. THE DOTS ARE SPACED 1.55" APART. A LIGHT LEAK IS PRESENT ON THE OUTBOARD EDGE OF FRAME 1103. FRAMES 1108 TO 1140 CONTAIN A PLUS

SECRET

Approved For Release 2008/02/01 : CIA-RDP78B04558A001000030015-2

Approved For Release 2008/02/01 : CIA-RDP78B04558A001000030015-2

DENSITY STREAK PARALLEL TO AND 4.Ø" FROM THE INBOARD EDGE. A FEW SMALL EMULSION DEFECTS ARE NOTED THROUGHOUT THE MATERIAL. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1353 AND FRAME 991 CONTAINS A BREAKDOWN SPLICE. A NUMBER OF OTHER BREAKDOWN SPLICES ARE POSITIONED BETWEEN FRAMES ELSEWHERE IN THE FILM.

D. BOTH SIDES: BOTH EDGES CONTAIN EDGE STATIC DISCHARGES AND FAINT ROLLER CHATTER TRACES. THE DATA CHAMBERS ARE UNDEREXPOSED. THE TITLED FRAMES ARE NUMBERED ØØØ1 TO 1999.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD WHERE WEATHER PERMITS.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE 35 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

/END OF MESSAGE/

Approved For Release 2008/02/01 : CIA-RDP78B04558A001000030015-2